

## SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR  
William B. Martin & Associates

3. ADDRESS OF OPERATOR  
2110 N. Sullivan, Farmington, N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 965' FNL and 830' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

**REQUEST FOR APPROVAL TO:**

### TEST WATER SHUT-OFF

## FRACTURE TREAT

## SHOOT OR ACIDIZE

## REPAIR WELL

**PULL OR ALTER CASING**

**MULTIPLE COMPLETE**

## CHANGE ZONES

**ABANDON\***

(other)

## Cement Production Casing

~~SUBSEQUENT REPORT OF~~

RECEIVED  
DEC 21 1982  
(NO

U. S. GEOLOGICAL SURVEY  
WASHINGTON, D. C.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11/29/82

Ran 2830' of new J-55 2 7/8" 6.4 lb/ft tubing cemented with 150 sacks Class B cement 2% Calcium Chloride (175.50 ft<sup>3</sup>). Baffle Plate at 2803'. Circulated cement to 1213 ft.

RECEIVED

JAN 6 1983

OIL CON. DIV.  
DIST. 3

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

**18. I hereby certify that the foregoing is true and correct**

SIGNED William B. Mart TITLE Operator DATE 12/6/82

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

ACCEPTED FOR RECORD

JAN 05 1983

FARMINGTON DISTRICT

**\*See Instructions on Reverse Side**

**NMOCC**