

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil ☒ gas ☐ other

2. NAME OF OPERATOR

Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR

313 Washington, SE, Albuquerque, NM 87108

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: Unit 'E' 1818' FNL & 582' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other)

SUBSEQUENT REPORT OF:

RECEIVED

AUG 22 1985^(N)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

**BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA**

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This is a request to extend the approval of the APD for a six (6) month period.

RECEIVED
AUG 26 1985
OIL CON. DIV.
DIST. 3

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 8/21/84

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC

M. MILLÉNPAICH
AREA MANAGER