

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other Instructions on Re-
verse Side)

Form 10-71 Rev. 11-1-1968
Budget Bureau No. 42 R1424
5. LEASE DESIGNATION AND SERIAL NO.

NM 6630

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Benson Mineral Group, Inc.		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR 3200 Anaconda Tower, 555 17th Street, Denver, Colorado 80202		8. FARM OR LEASE NAME Navajo 21	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1040' FNL & 1190' FEL Section 21-T22N-R7W		9. WELL NO. 1	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Rusty Chacra Extension	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6802 GR		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Section 21-T22N-R7W	
		12. COUNTY OR PARISH Sandoval	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Test ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-28-78: Left blowing from 20:00 6-27-78 until 18:00 6-28-78.
Making medium mist of water with slugs of water every
3-4 minutes. SI.

6-30-78: SI 48 hrs. CPC 400 psi. Blow for 3 hours through 3/4"
choke. Guaged 470 MCFD. SI, waiting on service unit to run tubing.

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul C. Ellison

TITLE Production Manager

DATE July 6, 1978

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

JUL 10 1978

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.