

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR 87108

313 Washington, SE, Albuquerque, NM

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: Unit "I" 1850' FSL & 990' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED
DEC 17 1982
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

5. LEASE

Jicarilla 54

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Chace Apache 54

9. WELL NO.

54-10

10. FIELD OR WILDCAT NAME

Chacon Dakota Undesignated Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3, T22N, R3W

12. COUNTY OR PARISH 13. STATE

Sandoval

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
7124' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Intend to perforate zones as follows:

Dakota "B": 6863', 6868', 6870', 6872', 6874', 6876', 6878', 6886',
6890', 6897' - 4 SPF

Dakota "A": 6770', 6772', 6776', 6778', 6780', 6782', 6784', 6786',
6788', 6791', 6799' - 4 SPF

Greenhorn: 6682', 6684', 6690', 6692', 6695', 6697', 6704', 6725'
4 SPF

Tocito: 6392', 6395', 6406', 6414', 6416', 6421', 6426', 6428',
6442', 6444', 6446', 6460', 6464', 6468', 6471', 6476',
6481', 6487', 6490', 6492', 6494', 6496' - 4 SPF

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED B. C. Mills TITLE President DATE December 15, 1982

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

DEC 17 1982

*See Instructions on Reverse Side

RECEIVED
OIL CON. DIV.
DIST. 3

APPROVED
DEC 23 1982
JAMES F. SIM
DISTRICT ENGINEER

MOCC

12-D
7589
9-78 Kd
80 Bdd

2-D
7570
4-78 Kd
78 Bdd

14-D
7520
4-78 Kd
75 Bdd

51 Pdd
6-78 Kd
29 Bdd
2-78 Kpc
2-78 Mdd

101
7590
11-78 Kd
90 Bdd

107
7628
9-80 Kd
75 Bdd

104
7555
5-79 Kd
100 Bdd

Chace Oil Co. '54'

11-79
7325
Kd

6-78 Kd
69 Bdd
7467

4-77 Kd
60 Bdd
7571

6-79 Kd
200 Bdd
7
7350
51 Pdd
51-6-9 Kd
29 Bdd

51 Pdd
51-6-9 Kd
32 Bdd

3
5-78 Kd
100 Bdd
7380

Thomas
7497
2-79 Kd
90 Bdd

80
7520
9-80 Kd
80 Bdd


7508
9-79 Kd
90 Bdd

35

Superior
Jic. 55
7335
2-81 Kd
44 Bdd

Superior
7990
3-81 Kd
150 Bdd

106
7380
9-79 Kd
200 Bdd



4

8-81 Kd
85 Bdd
7232

10-78 Kd
38 Bdd
7313

Bonanza Oil
7319
5-61 ?

Cole
7165
6-81 Kd
71 Bdd

Tanah
2790

1-81 Kd
20 Bdd

3

11
7140
7-82 Kd
130 Bdd

11-82 Kd
80 Bdd
7145

2

10-80 Kd
120 Bdd
7090

1-81 Kd
24 Bdd
7210
2823

9

Actex
Jic. 'D'
4-82 Kd
162 Bdd
6350

4-79 Kd
20 Bdd
5-79 Jic. 'D'
7085

Actex
Kd
6350

Cole

6
7077
6-81 Kd
150 Bdd

A+B

4
7087
5-81 Kd
80 Bdd

Cole

5-81 Kd
30 Bdd
7080

11

7
4-82 Kd
110 Bdd

7
7085
10-81 Kd
350 Bdd

4-81 Kd
5-81 Kd
225 Bdd

T 22 N R 3 W
1"=2000'
Sandoval Co., NM

RECEIVED

DEC 17 1982

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

NMOCC