

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM-19150
2. NAME OF OPERATOR Veteran Exploration, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 4643 S. Ulster, #1190, Denver, CO 80237	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL; 660' FEL Section 11-T20N-R3W	8. FARM OR LEASE NAME San Isidro //
14. PERMIT NO.	9. WELL NO. 16
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 6911' GR	10. FIELD AND POOL, OR WILDCAT Rio Puerco (Mancos)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SESE-16-20N-3W
	12. COUNTY OR PARISH Sandoval
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other) 30 day unrestricted test

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Approval is requested for a 30-day unrestricted production test. The purpose of this test is to aid in the design of the gathering system relative to injecting produced gas into the the San Isidro 13-11 well (13-T20N-R3W)

Estimated recoveries during the 30-day test period are 960 BBL and 2,250 MCF.

RECEIVED  
APR 9 1991  
OIL CON. DIV  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

*Richard Shuster*  
Richard Shuster

TITLE

Petroleum Engineer/Agent

DATE

3/11/91

(This space for Federal or State office use)

AREA MANAGER

APPROVED BY

*/s/ A. Abbe*

TITLE

RIO PUERCO RESOURCE AREA

DATE

APR 18 1991

CONDITIONS OF APPROVAL, IF ANY:

NMOCD

\*See Instructions on Reverse Side

ALL INFORMATION CONTAINED  
HEREIN IS UNCLASSIFIED  
DATE 8-1-90 BY SP-6 BJS