

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.

Lease No. SF 080533

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... <b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 5, 19 57

Well No. Pool Four 41 is located 675 ft. from [N] line and 650 ft. from [E] line of sec. 22

SE 22  
(1/4 Sec. and Sec. No.)

21N  
(Twp.)

5W  
(Range)

NMPH  
(Meridian)

Wildcat  
(Field)

Sandoval  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the Kelly Bushing ~~surface~~ above sea level is 7242 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Abandonment Work:

1. Plugged as follows: 50 sacks at 4800'.  
50 sacks at 3900'.  
50 sacks at 1560'.  
50 sacks at 250'.

2. Found top of cement at 83'.

3. Plugged casing with 10 sack cement cap. Installed marker and abandoned in accordance with USGS regulations, 9-1-57.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 South Behrend

Farmington, New Mexico

By B. W. Shepard

B. W. Shepard

Title Exploitation Engineer