

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio, Texas

Lease No. 5.7.078696-1

Unit 0

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 1, 1962, 19____

Well No. 5 is located 2475 ft. from N line and 2510 ft. from E line of sec. 21

Sec. 21 (1/4 Sec. and Sec. No.) 10N (Twp.) 3E (Range) 10W (Meridian)


Wilcox (Field) Cardinal (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6705 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Upon successful completion of the water shut-off operation this well was equipped with tubing, rods, pump jack, and an 100 bbl. oil tank. Since April 17 it has been pumped at the rate of 5 bbls. (75 gravity) per day.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Francis L. Harvey, Operator

Address Richita Hills, Texas

By Francis L. Harvey

Title _____