

(SUBMIT IN TRIPLICATE)

Indian Agency **Window Rock**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **Navajo Indian**

Lease No. **2-149-Sub-7176**

Stony Butte #11

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
JAN 16 1958
U. S. GEOLOGICAL SURVEY

January 14th, 19 **58**

Well No. **11** is located **950** ft. from **S** line and **685** ft. from **E** line of sec. **36**

SE 1/4 SE 1/4 Sec. 36
(1/4 Sec. and Sec. No.)

22N
(Twp.)

14W
(Range)

N.M.P.M.
(Meridian)

Stony Butte
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **6084** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Dakota test. Estimated total depth 4000'.

Surface Casing: 120' of 8-5/8" CD 24# 3-55 cemented to surface.
Production : Approximately 4000' of 5-1/2" CD 15.5# 3-55 cemented with 150 sacks.

If commercial production is indicated, the producing section will be sand-oil fractured.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **HENSON-NORTH-GARRE DRILLING CORP.**

Address **405 1/2 West Broadway**

Farmington, New Mexico

By **Alfred R. Guen**

Title **Vice-President**

RECEIVED
JAN 16 1958
OIL CON. COM.
DIST. 3

11

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914

10/10/1914



NEW MEXICO OIL CONSERVATION COMMISSION
Well Location and Acreage Dedication Plat

Section A.

Date 13 JANUARY 1958

Operator BENSON-MONTIN-GREER DRILLING CORP. Lease STONY BUTTE
Well No. 11 Unit Letter P Section 36 Township 22 NORTH Range 14 WEST NMFM
Located 950 Feet From THE SOUTH Line, 685 Feet From THE EAST Line
County SAN JUAN G. L. Elevation 5076.0 Dedicated Acreage 40 Acres
Name of Producing Formation Dakota Pool Stony Butte


1. Is the Operator the only owner* in the dedicated acreage outlined on the plat below?
Yes X No .
2. If the answer to question one is "no," have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes No . If answer is "yes," Type of Consolidation
3. If the answer to question two is "no," list all the owners and their respective interests below:

REF. GLO Plat dated 5 December 1893

Owner

Land Description

Section B



This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

BENSON-MONTIN-GREER DRILLING
(Operator) CORP.
Wood R. Greer
(Representative)

405 1/2 West Broadway
Address
Farmington, New Mexico

This is to certify that the well location shown on the plat in Section B was plotted from field notes of actual surveys made by me or under my supervision and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed 11 DECEMBER 1957

James P. Leese
Registered Professional
Engineer and/or Land Surveyor.

JAMES P. LEESE

Certificate No. 1463