16 727

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

UNITED STATES DEPARTM

SUBMIT IN TRIPLICATE.

SHOOTING OR ACIDIZING

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GFOL	OGICAL	SURVEY	

IENT	OF	THE	INTERIOR	verse side)	VII	•
	~1~		DVEV			

.4	_	20-0	603	9	500	
			ALLOTTES			MAME

SUNDRY NOTICES	AND	REPORTS	ON WELLS	
use this form for proposals to	drill or to	deepen or plug	back to a different	ľ

ABANDON*

CHANGE PLANS

(Do not use this form for propor Use "APPLICA"	NAVAJO	
OIL GAS WELL OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
DAN S DAVIS		DAVIS
3. ADDRESS OF OPERATOR		9. WELL NO.
4330mEAST TURNEY	PHOENIX ARIZONA	<u> #5</u>
4. LOCATION OF WELL (Report location of See also space 17 below.) At surface	learly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT WILDCAT
330' E, W LINE& 1650	o' N, S LINE SEC11 T22N R14W	SEC. 11 T22N R14W
	15. BLEVATIONS (Show whether DF, RT, GE, etc.)	12. COUNTY OR PARISH 18. STATE
14. PERMIT NO.	10. BLEVATIONS (Show whether Dr. B1, Ga, etc.)	
	5770 EST	San JAUN N MEX
16. Check A	opropriate Box To Indicate Nature of Notice, Repor	, or Other Data
NOTICE OF INTER	TION TO:	SUBSEQUENT REPORT OF:
	PULL OR ALTER CASING WATER SHUT-OFF MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING WELL ALTERING CABING

(Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones perti-

HOLE NUMBER FOUR NEVER CASED. HOLE 910' DEEP BUT BRIDGED AT 662' DURING SCHLUMBERGER LOGGING OPERATION. SINCE BAROID GAS DETECTOR INDICATED NO SHOWS BELOW 613. THE BRIDGE WAS NOT REMOVED. LIKEWISE DURING PLUGGING THE BRIDGE WAS UP TO 630 and was left in place. THE HOLE WAS CEMENT PLUGGED FROM 630 BACK TO500, FILLED WITH MUD AND A 35 CEMENT PLUG PLACED IN TOP OF HOLE. A FOUR INCH PIPE WITH CLOSED END WAS USED AS A MONUMENT AND METAL STAMPED WITH REQUIRED DATA . THIRTY SIX SACKS CEMENT USED, WORK COMPLETED 11&12 JUNE 66



S. GEOLOGICAL SURVEY

ABANDON MENT*

18. I hereby certify that the foregoing is true and correct

SIGNED DAN S DAVIS

OWNER TITLE

16JUNE66

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE

insil insolibrat insolibrat padisolibras

Hent To ettis Corp gre-