

Santa Fe Energy Company



7200 I-40 West
Amarillo, Texas 79106
806/359-2000
TWX 910-898-4111

May 5, 1982

State of New Mexico
Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico 87410

Re: Inspection Location
for Plugged Well

Gentlemen:

The following plugged and abandoned locations are ready to be inspected by your office. All commission forms have been filed with your office prior to this notice. Should you find anything wrong or out of order, please contact me at our Amarillo, Texas office as soon as possible.

- A. Carrica #1 - 910' FSL & 885' FWL, Section 10, T17N, R7W
McKinley County, New Mexico
- B. Fajada East #1
- 907' FNL & 456' FWL, Section 3, T20N, R10W
McKinley County, New Mexico
- C. Fajada West #1
- 1980' FNL & 660' FEL, Section 14, T20N, R11W
McKinley County, New Mexico
- ✓ D. Gallo #1 - 990' FSL & 660' FWL, Section 18, T21N, R9W
San Juan County, New Mexico

Sincerely,

Sammy N. Morgan
Drilling Engineer

Well Files

SNM/lcs

