5 BLM 1 Celsius-Fmn 1 Celsius-SLC Form 3160-5 UNITED STATES SUBMIT IN TRIPLI	Tile Form approved.  Budget Bureau No. 1004-0135 Expires August 31, 1985
(November 1983) (Formerly 9-331) DEPARTMENT OF THE INTERIOR verse side)	NM 16762
BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
i.	7. UNIT AGREEMENT NAME
OIL WELL OTHER  2. NAME OF OPERATOR	8. FARM OR LEASE NAME Witty
DUGAN PRODUCTION CORP.  3. ADDRESS OF OPERATOR	9. WELL NO.
D.O. Boy 208 Farmington NM 87499	10. FIELD AND FOOL, OR WILDCAT
4. LOCATION OF WELL (Report location clearly and in accordance withinky histoclean place 17 below.)  At surface	Undesignated Gallup
1980' FNL - 660' FWL  BUREAU OF LAND MANAGEMENT FARMINGTON PEROURCE AR	Sec.12, T23N,R10W, NMPM
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, ET, GE, etc.)	12. COUNTY OF PARISH 13. STATE
6755' GL; 6767' RKB	San Juán   NM
16. Check Appropriate Box To Indicate Nature of Notice, Report	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
REPAIR WELL (NOTE: Report	
M.I.& R.U. Four Corners Drilling Company rig #9. Spud 12½" hole at 8:45 AM on 6-1-85. Drilled to 210'. Ran 7 joints of 8-5/8" OD, 24#, 8 Rd, J-55, ST&C casing (T set at 202'. Cemented with 135 sacks class "B" plus 2 (Total cement slurry = 159 cf). P.O.B. at 12:00 noon 6-1-85. Circulated ½ bbl good cement. W.O.C. 12 hour Pressure tested casing & BOP to 600 psi for 30 minutes drilling out.	ded .E. 190') % CaCl. on s.
18. I hereby certify that the foregoing is true and correct	~
TITLE Geologist	ACCEPTED FOR RECORD
(This page for Federal or State office use)	IIIN AT 100T
APPROVED BY	JUN 05 1985
CONDITIONS OF APPROVAL, IF ANY:	FARMINGTUN RESOURCE AREA

\*See Instructions on Reverse Side NMOCC