


(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe**  
Lease No. **SF 080500**  
Unit **Anderson "A"**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	RECEIVED	SUBSEQUENT REPORT OF WATER SHUT-OFF <b>Surface</b>	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS	JUL 3 1958	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**July 1, 1958**

**Anderson "A"**  
Well No. **2** is located **990** ft. from **S** line and **990** ft. from **E** line of sec. **25**  
**SW 1/4 Section 25** **24N** **2W** **N.M.P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Undesignated (Pictured Cliffs)** **Rio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is **7535** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**SPUN: 8:30 P.M., 6/19/58.**

**Ran & set 10-3/4" casing at 211' & cemented with 200 sacks regular cement 2% CaCl. Cement circulated to surface.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **SKELLY OIL COMPANY**  
Box 426  
Address **Farmington, New Mexico**  
By \_\_\_\_\_  
Title **District Superintendent**