



Sec. 26

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 60202
Unit _____

RECEIVED

SEP 6 1957

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 3, 1957

Well No. 1 is located 1950 ft. from [N] line and 1700 ft. from [E] line of sec. 26

SW 1/4 of SE 1/4, Sec 26

(1/4 Sec. and Sec. No.)

Wildcat

(Field)

T-24-N R-7-W

(Twp.)

(Range)

Rio Arriba County

(County or Subdivision)

N. M. Principal

(Meridian)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 6724 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The Federal 4-26 #1 was spudded 8-19-57. Surface 8-5/8" casing was cemented at 492' 2/300 SI. On the last day of the month drilling was being continued at 4966'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Co. of Texas

Address P. O. Box 1249

Houston 1, Texas

By Ray M. Dickerson
Title General Engineer