5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

DEPARTMENT OF THE INTERIOR	CONTRACT 36
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Vicarilla Apache
CHAIDDY MOTICES AND DEDODES ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	A STATE OF THE STA
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil Gas G	NORTHGUET HAYMES
well well other	9. WELL NO.
2. NAME OF OPERATOR	10
CONTINENTAL OF COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Odeso Gorang
P. C. Box 459, 1139 N.M. 0024:	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	SEL 21 TZ4/N R5W
AT SURFACE: 1849 FAL \$1849 FELL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: _	Restante No
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15 FLEVATIONS (CHOW DE VOS AND WE
	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	GARA OF
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
CHANGE ZONES	
ABANDON*	
(other)	
including estimated date of starting any proposed work. If well is discussived and true vertical depths for all markers and zones pertinent of is groposed to alean out fill in the contraction as follows - MIRU, fill well pull they. - Rekun they w/ + 350 of 121" Language - Sling three piece of C.O. to 5920' as - Relun grod eaget found woll; Subsurface Safety Valve: Manu. and Type	JUN 12 1979 OIL CON. COM. DIST. 3
	Set @Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED Was P. Putterfeel TITLE Same Suy	DATE 5-25.79
(This space for Federal or State offi	
APPROVED BY	DATE
CONDITIONS OF APPROVAL, IF ANY CISCAS DURANGO 4	
GEA	
FILE,	

*See Instructions on Reverse Side