

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

FEDERAL 3-19-42
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 000031
Unit A

Sec. 19

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

12-4, 1957

Well No. 3-1951 is located 660 ft. from N line and 660 ft. from E line of sec. 19

NE 1/4 of NE 1/4 Sec. 19
(1/4 Sec. and Sec. No.)

24N
(Twp.)

7W
(Range)

13PM
(Meridian)

Undesignated
(Field)

Elko Apache County
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7269 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud logging jobs, cementing points, and all other important proposed work)

The Federal 3-1951 was spudded on October 28, 1957. Surface casing (8 5/8") was cemented at 412 feet with 240 sacks cement. An estimated 110 sacks of cement were circulated. A 7 7/8" hole was being drilled at 1700' at the end of the month.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Co. of Texas

Address P. O. Box 1249

Barton 1, Texas

By Charles A. Lintrop

Title Field Foreman

