



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

FEDERAL 3-1971
Budget Bureau No. 42-R358.4
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 080004
Unit A

RECEIVED

NOV 8 1957

U. S. GEOLOGICAL SURVEY

Sec. 19

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

11-4, 1957

Well No. 3-1971 is located 660 ft. from N line and 660 ft. from E line of sec. 19

NE 1/4 of NE 1/4 Sec. 19
(1/4 Sec. and Sec. No.)

24N
(Twp.)

7W
(Range)

N19PM
(Meridian)

Undesignated
(Field)

El Paso County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7289 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The Federal 3-1971 was spudded on October 28, 1957. Surface casing (8 5/8") was cemented at 122 feet with 240 sacks cement. An estimated 110 sacks of cement were circulated. A 7 7/8" hole was being drilled at 1700' at the end of the month.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Co. of Texas

Address P.O. Box 1249

Houston 1, Texas

By Charles H. Lantry

Title Field Foreman