

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 080031

Unit A

Sec. 19

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|--|--|---|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | X |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 2, 1957

Well No. 3-13 #1 is located 650 ft. from N line and 650 ft. from E line of sec. 19

SE 1/4 of Sec. 19
(1/4 Sec. and Sec. No.)

21-N
(Twp.)

7-W
(Range)

11-11
(Meridian)

Undesignated
(Field)

Rio Arriba County
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7289 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was drilled to a TD of 6202' using a 7 7/8" bit. An oil string of 5 1/2" casing was set at 6200 ft. and cemented w/ 200 sacks cement. At the end of the month a pulling unit was being moved in to complete the well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of Texas

Address P.O. Box 1531

Wilmington, New Mexico

By Charles H. Lantry

Title Field Foreman