

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM-03595
Unit Judy Federal

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 21, 1960

Well No. 2 is located 1650 ft. from S line and 1980 ft. from W line of sec. 17

NW/4 SW/4 Sec. 17
(1/4 Sec. and Sec. No.)

24N
(Twp.)

7W
(Range)

NMPM
(Meridian)

Hecrito(Gallup)
(Field)

Rio Arriba
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

August 16, 1960 - Set 221 ft. of 8-5/8" OD 24# smls. casing.
Cemented casing with 125 sacks of 50-50 pox mix 4% gel.
Circulated cement to surface,
Drilling Ahead



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DOREMAN PRODUCTION COMPANY

Address 836 Mercantile Dallas Bldg.

Dallas, Texas

By _____

Title General Manager

