

(SUBMIT IN TRIPLICATE)

Indian Agency \_\_\_\_\_


WELL-3  
File-1

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Sierrita

Allottee Contract #120

Lease No. \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	2
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 4, 1957

Well No. "A" 14-13 is located 1760 ft. from [N] line and 1000 ft. from [E] line of sec. 1313

SE/4 NE/4 13	24N	4W	1313
(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
Walden FC	San Antonio	New Mexico	
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the ~~ungraded ground~~ above sea level is 6015.0 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 11" hole 9 PM 12-27-56. Drilled to 131' and set 130.22' of 7-5/8" OD J-55 240 8-20 casing w/Reeve guide shoe at 130.00'. Cemented to surface w/100 oz seg w/22 GEL. PM 4 on 12-28-56. After 24 hrs WAS casing tested OK. Drig ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ROCKWELL PRODUCTION CORP.

Address 220 Stone Building

Albuquerque, New Mexico

RAY PHILLIPS

By Ray Phillips

Title Asst. Mgr., Prod. Dept.

