



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Jicarilla Indians**
Lease No. **Contract No. 48**
Unit _____
Co. **Les. 149113**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Report of drill stem test	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Jicarilla Apache Tribe of Indians "B" Hobbs, New Mexico June 20, 1955

Well No. **1** is located **990** ft. from **{N}** line and **990** ft. from **{E}** line of sec. **17**

NE/4 of NE/4 of Sec. 17 **24-N** **4-N** **R24N**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wilcox **Elizabethton** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **later** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run drill stem test on 6-18-55 from 2743 to 2845 feet. Tool open 30 minutes, weak blow and shut in 8 minutes. Initial and final mud 13.5 lb. Minimum and maximum flow 0. Shut in pressure after 30 minutes 0. Recovered 3' drilling mud. Chloride in test negligible.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shutle Oil & Refining Company**

Address **Box 2347**

Hobbs, New Mexico

By **[Signature]**

Title **Agent**



