

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 1541
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

JOHN S. DASHKO #1

Sec. 11, T24N, R7W
NE/4SE/4
Rio Arriba County, NM

SLOPE TEST

Depth

Hole Deviation

344'
1980'
3134'
4280'
5254'
6001'
6988'

$\frac{1}{4}^{\circ}$
 $\frac{3}{4}^{\circ}$
 $1\frac{1}{2}^{\circ}$
 $1\frac{1}{2}^{\circ}$
 $1\frac{1}{4}^{\circ}$
 $1\frac{1}{4}^{\circ}$
 1°


RECEIVED

DEC - 7 1983


OIL CON. DIV.
DIST. 3

STATE OF NEW MEXICO)
) SS
COUNTY OF SAN JUAN)

I, Robert L. Bayless, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.



Subscribed and sworn before me this 7th day of December, 1983.


Notary Public

My Commission Expires: 9-20-84

