

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY SAN JUAN GAS CORPORATION, 1716 1st Natl. Bldg., Tulsa, Oklahoma
(Address)

LEASE Federal WELL NO. 12-B UNIT P S 12 T 24 N R 2 W

DATE WORK PERFORMED 10-6-56 POOL Lindrita

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Well making water following fracture treatment of perforations at 3450-64'. Set Baker wire line bridge plug at 3442' and perforated one foot at 3425'. Swabbed 25 barrels of water per hour; had cement job. Waiting on tools to recomplete.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test _____

Oil Production, bbls. per day _____

Gas Production, Mcf per day _____

Water Production, bbls. per day _____

Gas-Oil Ratio, cu. ft. per bbl. _____

Gas Well Potential, Mcf per day _____

Witnessed by _____

(Company) _____

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold

Title Supervisor Dist. # 3

Date MAY 8 1957

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Robert C. Pearson

Position Vice President

Company San Juan Gas Corporation
1716 First National Building
Tulsa, Oklahoma



OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Received 4		
DISTRIBUTION		
	NO. FURNISHED	
Operator	2	
Santa Fe	1	
Proration Office		
State Land Office		
U. S. G. S.		
Transporter		
File	1	✓