Form 9-331 (May 1963)

SUBMIT IN THITLICALLY Budget Bureau No. 42-R1424. [Other instructions on reverse side] | S. Lease Designation and Berlay No. UNITED STATES

DEPAR	IMENI OF THE INTENT		sr-078959 /
	GEOLOGICAL SURVEY		G. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NO	OTICES AND REPORTS (ON WELLS	· / · · ·
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			/
			7. UNIT AGREEMENT NAME .
OIL XX CAS OTHER			Escrito Gallup Unit
			8. FARM OR LEASE NAME
NAME OF OPERATOR			Escrito Gallup Unit
Bco, Inc.			9. WELL NO.
3. ADDRESS OF OPERATOR			• • • • • • • • • • • • • • • • • • • •
P.O. Box 669, Santa F	'e, N.M. 87501		4 (Formerly Fed 2-7
A LOCATION OF WELL (Report locally	on clearly and in accordance with any	State requirements.	1
See also space 17 below.) At surface			Escrito Gallup 11. SEC., T., R., M., OR BLK. AND
990 FML and 790 FSL Sec 7 T24N R7W NMPM			BURYEY OR AREA
1) 12 and 100 102 -		•	
••	· 		7-24N-7W NMPM 12. COUNTY OR PARISH 13. STATE
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	1
	GR 7163		Rio Arriba NM
	A D T 1 J	Value of Natice Report or C	Diher Data
16. Check	Appropriate Box To Indicate 1		
NOTICE OF I	NTENTION TO:	BUBSEQ	UDNT REPORT OF:
	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
TEST WATER SHUT-OFF	MULTIPLE COMPLETE	FRACTURE TREATMENT X	-1 1 1
FRACTURE TREAT	ABANDON®	SHOOTING OR ACIDIZING X	ABANDONMENT*
SHOOT OR ACIDIZE	CHANGE PLANS	(Other)	W.N
REPAIR WELL,		Completion of Recolly	s of multiple completion on Well oletion Report and Log form.)
(Other)	- convertees (Clearly state all pertine		a a se continue de la confine any
proposed work. It well is a	irectionally drilled, give subsurface loc	ations and measured and true vertic	al depths for all markers and zones perti-
nent to this work.)	1 1 -1		*** *** *** *** *** *** *** *** *** **
			h 2 shots per foot:
5006-5014 5	8aker P-1 bridge plug at 8876-5886; 5866-5876; 58	861-5866; 5822-5826; 5	816-5819 and 5806-
5900-5914, 5	total of 100 shots.	•	
5 00 70 Cores bood f	Frac with 250 gallons 7	1/2% acid and 500 gal	lons 15% acid. Sand
water fracke	er. Breakdown 1700 #'s,	avg. treating pressur	ce 2050 #'s, avg.
injection ra	to 33 RPM.		
_			
Country and 11 and 11	aced on numn jack. Prod	uction test run 5-29-7	73 20 barrels oil, 5
Swabbed well and placed on pump jack. Production test run 5-29-73 barrels water and 30 MCF.			
parrels water	st and so nor.		<u> </u>
			FOUN
NOTE	n well shuting off perf	orations of (6006-602)	2) / 01 / 10 %
Bridge plug still in	a well shating off port		
			1
Attachments 11:1	- tracting report.		JUL II 1072
Copies of Halliburt	on creating report.	3C.	ami on 1975
2 copies of log to	USGS and one copy to OC		CON. COM
			DIST. 3
>			
18. I hereby certify that the foreg	soling is true and correct		7-10-73
Marger	TIME TIME	President	DATE
SIGNED ACCOUNTY			
(This space for Leueral or Si	ate office use)	<u>.</u>	
_	TITLE		DATE
CONDITIONS OF APPROVAL			
			•