

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Tribal

Allottee **Jicarilla "B"**

Lease No. **Contract #42**

Tract #127

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	Surface	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 2, 1957

Well No. **Jicarilla "B"** is located **660** ft. from **[S]** line and **660** ft. from **[W]** line of sec. **32**

SW/4 Section 32
(1/4 Sec. and Sec. No.)

25N
(Twp.)

3W
(Range)

N.M.P.M.
(Meridian)

Dakota (Undesignated)
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SPUDDER: 11:30 A.M., October 3, 1957.

Ran 10 Juts. 10-3/4" casing set at 324' & cemented with 300 sacks regular cement 2% CaCl. Cement circulated to surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company **SKELLY OIL COMPANY**

Box 426

Address **Farmington, New Mexico**

By **(Signed) P. E. Cosper**

Title **District Superintendent**

10/21/19

10/21/19

