

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo Tribal
Allottee Navajo
Lease No. Contract A-68

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Plug Back and Testing Cement Job</u>
	<u>Special Perforations</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 9, 1959

Well No. 20 is located 790 ft. from N line and 790 ft. from W line of sec. 31

1/4 Sec. 31 (1/4 Sec. and Sec. No.) 31 (Twp.) 31 (Range) 31 (Meridian)

State - California San Bernardino County San Bernardino (State or Territory) (County or Subdivision)

The elevation of the derrick floor above sea level is 8734 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Run and set Baker magnesium bridge plug at 7020-12'. Dumped 1 sack of Calceol on top of bridge plug. Plugged back to 7025'.

Perforated 7" casing for dry test, 6090'-91' with 4 Water Dyna-jets.

Drill then Test No. 1 in casing perforations 6090'-91'.

Took open 1 hour with 1/8" bottom choke and 1" top choke. Gas to surface in 15 minutes and continued as small blow throughout test. Gas too small to measure. Recovered 420' of gas cut mud. 177 1704. 777 1804. 30 minute SHUT 2104.

Hydrostatic pressure 2104' in and out.

Continued perforating 7" casing as follows: 6012-14' (4") 16 holes, 6014-40' (16") 64 holes, 6074-90' (16") 64 holes for a total of 36" and 144 holes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY
Address Box 425
Farmington, New Mexico

By (Signed) P. E. Cosper

Title _____