

F. Loc. 790/N; 790/W Elev. 6456 Spd. 4-50 Comp. 5-10-4 TD 7-1-5 PB 7-1-5

Casing S. 1074 @ 298 W 200 Sx. Int. 17 @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
Csg. Perf. _____ Prod. Stim. _____
29-502061 DE 100 SX

BO/D
I.P. MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. *Westing*

[illegible]

P
 D
 C
 Otero Gal RA 31 25N 5W 1D
 Jan. Feb. Mar. Apr. May June July Aug. Sept. Oct. Nov. Dec.
 Skelly Gil Jicarilla "B" No 20



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		RECEIVED JUN 2 1971 OIL CON. COM. DIST. 3	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Tribal Contract No. 68		
2. NAME OF OPERATOR Skelly Oil Company			7. UNIT AGREEMENT NAME		
3. ADDRESS OF OPERATOR 1860 Lincoln Street - Denver, Colorado 80203			8. FARM OR LEASE NAME Jicarilla "B"		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790' FNL & 790' FWL of Section 31-25N-5W Rio Arriba County, New Mexico			9. WELL NO. 20		
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6736' DF		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31-25N-5W	
				12. COUNTY OR PARISH Rio Arriba	
				13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☒ &
Abandon
Gallup
Zone.(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/28/71 MI&RU Aztec Well Service Workover rig.

Pulled rods (Gallup Zone). Unable to release (Dakota zone) tubing string from Baker Model "D" packer. Cut (Dakota) tubing string at 7,000' and recovered. Went in hole w/overshot and jars and latched on to Dakota tubing at 7,000'. Unable to jar loose from Model "D" Packer.

Went in hole w/1 joint of washover pipe & washed over tubing to top of Model "D" packer.

Went in hole w/overshot & jars & recovered tubing, seal assembly & 2 joints of tail pipe.

Went in hole w/Halliburton retrievable bridge plug & RTTS packer. Found hole in 7" csg. between 2198' and 2632'. Set retrievable bridge plug at 3210' & RTTS packer at 2135'.

Squeezed hole in 7" casing w/200 sacks of Class "A" Cement w/1000#. Held 1000# on cement job for 8 hours. Went in hole w/bit & 2 3/8" tubing. Found top of cement at 2146'.

Drilled cement from 2146'-2627'. Pressured 7" casing to 1000#, held OK. Pulled tbg. & bit.

Ran tubing w/RTTS packer & fishing tool. Fished out bridge plug at 3210'. Ran tubing to 5190' and tested casing; held OK.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Operations Sup't. DATE May 27, 1971.

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

JUN 1 1971

1 COPY FOR STATE

