Form 9-331 a (Feb. 1951)

i	1		
1	i		
!			
		. 	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office San	ta Fe-
Lease No. SE	41335
Unit	

SUNDRY NOTICES AND REPORTS ON WELLS 1986

NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	-	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	-	
(INDICATE ABOVE BY CHECK MAR	RK NATI	URE OF REPORT, NOTICE, OR OTHER DATA)

			February	27		, 19 58
Well No. 30-H is located	.1962. ft. i	from $\left\{ egin{array}{c} oldsymbol{\mathbb{N}} \ oldsymbol{\mathbb{S}} \end{array} \right\}$ line	e and	f t. from $\left\{ ight.$	E line of	sec
SE/4 Section 30	25N	-17	N. M. P	. M.	_	
Jailan	Rio Ar	ribe	(Merid	lian)	dexico	
SE/A Soction 30 (1/2 Sec. and Sec. No.) (Field) (Field)	(Co	unty or Subdivision)		(Stat	e or Territory)	

The elevation of the derrick floor above sea level is 7636... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 3800 foot Pictured Cliffs So. Well. 100' of 24th. 8 3/4" surface casing comessed with 100 sacks 3800' of 14th 5 1/2" production XXXIIII casing comested with 150 sacks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.			
	San Juan Gas Corporation		
Address	100 Shell Building		
	Tuisa, Oklahema	By Robert Clarson	
		Title Vice-President	