Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FØRM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

CONTRACT # 34 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian. Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals JICARILLA APACHE 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well X Oil Well 8. Well Name and No. 2. Name of Operator JICARILLA C 25 9. API Well No. TEXACO EXPLORATION & PRODUCTION, INC. 3. Address and Telephone No. 30 039 05818 10. Field and Pool, or Exploratory Area 3300 North Butler, Farmington, New Mexico 87401 (505)325-4397 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) OTERO, GALLUP 11. County or Parish, State 1980' FSL, 660' FWL, NW 1/4, SW 1/4 sp. L Sec. 27 T 25 N / R 5 W RIO ARRIBA Co., NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION X Abandonment Notice of Intent Change of Plans New Construction Recompletion Non-Routine Fracturing Plugging Back Water Shut-Off Casing Repair Conversion to Injection Y Final Abandonment Notice Altering Casing Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco E. & P. Inc. has performed the following work on the subject well:

8/11/92 MIRU, NU BOP, POOH w/ TBG, and packer. GIH w/ bit & scraper to 6190'. Set cement RET @ 6030'. Test to 2000#, OK. Squeeze perfs w/ 73 SX G neat cmt. 35 SX in perfs, 28 between RET and perfs, 10 SX on top of RET. PBTD @ 5950'. Test csg. GIH w/ PKR. Found top hole between 790' and 825'. Also found 630' of bad csg fr 4270' to 4900'. GIH, tag cmt at 5950'. Spot 182 SX G neat fr 5950' to 4420'. GIH, tag cmt at 4428'. Perf 2 holes at 4420'. Set RET at 3990'. Spot 93 SX G neat, 51 in csg, 42 behind csg. Spot 166 SX G fr 3990' to 2600'. Perf 2 holes at 2600'. Set RET @ 2510'. Pump 37 SX 35/65 POZ under RET. Spot 11 SX POZ fr 2510' to 2365'. Perf 2 shots @ 2365'. Set RET @ 2165'. Spot 77 SX fr 2165' to 1130'. Perf @ 1130'. Set RET @ 930'. Pump 74 SX. Tried to pump down 5 1/2" csg up 10 3/4" ann. Pressure up to 2000#. Perf @ 350'. Pump 103 SX down 5 1/2" up 10 3/4". Circ. to surface. Erect P&A marker.

ENTIRE P&A JOB DONE UNDER BLM SUPERVISION.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.

_{Title} Area Manager	Date 9/22/92
	A PPROVED
Tide	Date 10 1092 AREAMANAGER
	Title Area Manager Title

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

İ	