

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Jicarilla
Lease No. Contract No. 41
Unit Tract No. 86

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of Casing</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 24, 1954

Well No. 1 is located 915 ft. from N line and 330 ft. from E line of sec. 30

NE 1/4 Sec. 30 (1/4 Sec. and 1/4 Sec. No.) 25N (Twp.) 1W (Range) N.M.P.M. (Meridian)

Jicarilla (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the ~~surface~~ ^{ground} above sea level is 6980 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cemented 10 3/4" OD, 32.75#, casing at 250' RBM, with 250 sacks portland cement, WOC 48 hours. Tested casing with 1000 lbs. for 1 hour, No pressure drop.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Co.

Address 1755 Glenarm

Denver, Colorado

By _____

Title District Superintendent

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
REMARKS IN TRAIL

MONTA RESISTO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHORTAGE
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDING
NOTICE OF INTENTION TO TEST WATER SHORTAGE	SUBSEQUENT REPORT OF ALKALINE DRAINAGE
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACID DRAINAGE	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR

(INDICATE AS MANY OF THE FOLLOWING AS ARE APPLICABLE TO THE TYPE OF REPORT COVERED ON OTHER SIDE)

is located in _____ from _____ time and _____ from _____ time of day.

(1) (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

The location of the debris foot above sea level is 11.4 ft.

DETAILS OF WORK

The Department has also been asked to provide information regarding its efforts to ensure that all employees are aware of their rights under the law, and to provide training to management personnel on how to handle complaints.

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 08-19-2010 BY 60322 UCBAW/SJS

• 17 •



© 2000 by the American Psychological Association or one of its allied publishers. This article is intended solely for the personal use of the individual user and is not to be disseminated broadly.

.....a