

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Jicarilla

Lease No. Contract No. 41

Unit Tract No. 86

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Drill Stem Test	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 4, 1954

Well No. 1 is located 915 ft. from [N] line and 330 ft. from [E] line of sec. 30

NE 1/4 Sec. 30 (R. Sec. and Sec. No.) 25 N (Twp.) 14 W (Range) N. M. P. M. (Meridian)

Jicarilla (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the ~~drill floor~~ ^{ground} above sea level is 6980 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

PICTURED CLIFFS

Drill Stem Test 3214'-3264'; tool open 1 hour, shut in twenty minutes, light blow 22 minutes, recovered 330' drilling mud, flowing pressure 160#, SIP 500#. (1-13-54 Drill Stem test the Mancos 5314'-5377'; tool open 1 1/2 hours, recovered 200' mud, flowing pressure Zero, SIP 875#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Co.

Address 1755 Glenarm

Denver, Colorado

By H. R. Roberts

Title District Superintendent

Land Office
 State of
 United States

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED
 GEOLOGICAL SURVEY
 DEPARTMENT OF THE INTERIOR
 WASHINGTON, D. C.

SUNDRY NOTICES AND REPORTS ON WELLS

REPORT ON INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
REPORT ON INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF STOPPING OR ABANDONING
REPORT ON INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING Casing
REPORT ON INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REPAIRS AND RE-DRILL
REPORT ON INTENTION TO SHUT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONING
REPORT ON INTENTION TO PUMP OR WATER CASING	REPORT ON INTENTION TO ABANDON WELL

(INDICATE ABOVE EACH REPORT THE DATE WHEN REPORT WAS MADE)

_____ is located _____ ft. from _____ line and _____ ft. from _____ line of section _____

_____ (Name)
 _____ (County)
 _____ (State)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

State in detail and explain briefly the nature and extent of the work done on the well, and the results obtained. (This space is to be filled in by the operator and the owner of the well.)

I understand that this report will be used by the Geological Survey for the purpose of determining the location and character of the well, and for the purpose of determining the value of the well.

Operator of the well _____

Owner of the well _____

Witness _____

THESE REPORTS ARE REQUIRED BY THE GEOLOGICAL SURVEY