(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Indian Agency	diametila	
Contract	No.	125
Allottee		
Lease No.	10 01	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO REDRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY PROFILE OF INTENTION TO ABANDON WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY PROFILE OF INTENTION TO ABANDON WELL	NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF WATER SHUT-OFF
Substitution of some flags	NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
		i	SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SICARILLA APACHE TRIME	Parmington, No.	K., July 18,	, 19_56
	ed 1167 ft. from N line and 90	ft. from E line of	f sec 25
(14 Sec. and Sec. No.)	(Twp.) (Bange)	(Meridian)	•
(Field)	(County or Subdivision)	(State or Territor))

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, coment-ing points, and all other important proposed work)

afree w/59,640 gale, unter and 112,000/ send. Ave. inj. rate 49 bbls./win.

I understand	that this plan of work must receive approval in writing by the Bushle Cill & Refining Company	Geological Survey before operations may be commenced.
Address	Des 1268	COPY ORIGINAL R. M. LILLY
	Parmington, N. N.	Ву
		Title Pist. Supt.
	S. S. GOVERNMENT PRINTING OFFICE	16-64275-7