



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_  
**Jicarilla Tribal**  
Allottee **Jicarilla #6**  
Lease No. **Contract #34**  
**Tract #79**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<b>Surface</b>	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**February 5, 1957**

**Jicarilla #6**  
Well No. **14** is located **1190** ft. from **N** line and **1190** ft. from **E** line of sec. 27  
**NE/4 Section 27** (1/4 Sec. and Sec. No.) **28N** (Twp.) **9E** (Range) **N.M.P.M.** (Meridian)  
**Wildcat** (Field) **Rio Arriba** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**SPUDDED: 5:00 P.M. January 31, 1957**

**Set 10-3/4" casing (11 jnts. 310') at 322' with 300 sacks regular cement (1% CaCl). Circulated**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shelly Oil Company**

Address **Box 426**

**Farmington, New Mexico**

By (Signed) **F. E. Cosper**

Title **District Superintendent**

