



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio
Lease No. 7000410
Unit Field

AUG 27 1959

U.S. GEOLOGICAL SURVEY
WASHINGTON, D.C. 20500

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 21-1-10 is located 100 ft. from N line and 100 ft. from E line of sec. 10

10 (1/4 Sec. and Sec. No.) 10 (Twp.) 10 (Range) 10 (Meridian)
10 (Field) 10 (County or Subdivision) 10 (State or Territory)

The elevation of the derrick floor above sea level is 1000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 8-21-59 Total Depth 3100'.
Run 16 joints of 1 1/2", 8-55, 15-21 casing (3500') set at 3100' with 13 sacks regular cement, 13 sacks Mazak, 1/40 strata-crete 6/24, 2 24 Gel, followed with 50 sacks neat cement.

Hold 1000, 30 minutes.

Top of cement by temperature survey at 3100'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 907
Furlington, New Mexico

By ORIGINAL SIGNED J.J. TILLERSON

Title Petroleum Engineer

1970
DIST. 3
L. COR. CORN