

(SUBMIT IN TRIPLICATE)

Land Office **New Mexico**
04089

Lease No.

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

FEB 12 1963

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

X

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

February 7

19 63

Federal

Well No. 19-1-H is located 990 ft. from ~~XX~~ line and 1090 ft. from ~~XX~~ line of sec. 19.SW/4 Section 19
(1/4 Sec. and Sec. No.)25-N
(Twp.)1-W
(Range)N.M.P.M.
(Meridian)Cavalin Pictured Cliffs Ext.
(Name)Rio Arriba
(County or Subdiv. Name)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7463 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands, show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On January 9, 1963, this well was plugged & abandoned in the following manner:

1. Spotted a 15 sk. cement plug across perms (3550-3604). Pulled tubing.
2. Shot 5 1/2" casing @ 1012'. Spotted a 15 sk. cement plug across cut off & pulled casing.
3. Spotted a 10 sack cement plug in surface w/ 4' x 4" hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**Address **Box 990****Farmington, New Mexico**

By

Title **Petroleum Engineer**