



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency **Jicarilla**

Allottee **Jicarilla Tribal**

Lease No. **Lease No. 64**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**RECEIVED**  
JAN 23 1959  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

December 23rd, 19 58

Well No. **11-X** is located **1850** ft. from **[N]** line and **850** ft. from **[E]** line of sec. **19**  
**NW/4 SW/4 Sec. 19** **25N** **4W** **N.M.P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**S. Blanco PG Mnt.** **Rio Arriba** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6953** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud jobs, cementing points, and all other important proposed work)

- 11-11-58** TD 97' MEK. Set 3 joints 88' of 8-5/8" OD 24# J-55 casing at 97' with 70 sacks cement, circulated to surface.
- 12- 8-58** Pressured up on casing to 500#. No pressure decrease in 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **EL PASO NATURAL GAS COMPANY**

Address **Box 997**  
**Farmington, New Mexico**

By **E. S. Oberly**  
Title **Division Petroleum Engineer**