

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. _____

Unit _____

RECEIVED

OCT 7 1958

SUNDRY NOTICES AND REPORTS ON WELLS
FARMINGTON NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 11 is located 150 ft. from N line and 70 ft. from E line of sec. 21
1 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
1 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7374 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3 5/8" cas. set at 107' with 125 ex. Tested with 1000 for 15 min.
Water shut off ok. 5" cas. set at 3490' with 150 ex. 1000.
Tested with 1000 for 15 min. Shut off ok.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Much-Chislan

Address 1000, 1000

By Jay J. Harris

Title Geologist