


NEW MEXICO OIL CONSERVATION COMMISSION
NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator EL PASO NATURAL GAS COMPANY		Well Name and Number Alcorilla 07 36 (DCH)	
Location of Well Unit W Sec. 19 Twp. 28N Rge. 05W		TYPE OF TEST →	Annual - (Give Year) 1972
UPPER COMPLETION	Reservoir or Pool Pictured Cliffs	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT
LOWER COMPLETION	Reservoir or Pool Chisna	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT
		☐ NEW ☐ OWWO	Production String ☐ CASING ☐ TUBING
			Production String ☐ CASING ☐ TUBING

Date	Upper Zone		Lower Zone		
	Shut-in		Shut-in	Flow Test	
	Casing	Tubing	Tubing	Tubing	Flow Rate
9/18/72	281	281	238		
9/19/72	283	283	293		
9/20/72	295	295	319		
9/21/72	300	300		101	233 MCF/D
9/22/72	302	302		105	193 MCF/D

Remarks:




The results of this test indicate (No Packer Leakage) (Packer Leakage) in this well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED SEP 28 1972, 19____
NEW MEXICO OIL CONSERVATION COMMISSION
BY A R Kendrick
PETROLEUM ENGINEER DIST. NO. 3

OPERATOR EL PASO NATURAL GAS COMPANY
BY J. A. Jones
TITLE Well Test Engineer
DATE _____



E P N G
 Annual Packer Leakage Test
 1972
 JICARILLA 67 #6 (PC)
 Unit H Sec.19-25-05
 Rio Arriba Co., New Mexico

o PC Zone • CH Zone