OR ()	m 9- Feb. 1	951)		
			~~~~	

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Jev	Mexico
Lease No	014	Lä
Unit	Car	loer

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

				Getober 19	19.22
Well No. 1 is locate	ed 1650 ft	t. from $N$ line ar	nd 990 ft. from	h W line of sec.	24
MW Sec. 24	258	*	H.M.P.N.	•	
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
Tapacito P. C. Ext.		Rio Arribi		Hew Mexico	
(Field)		(County or Subdivision)	(8	tate or Territory)	

The elevation of the derrick floor above sea level is 7213 ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

This plat is re-issued to show corrected elevation.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	il Paso Satural	Gas Company		
	Box 991			
	Farmington, Nev	Mexico	Ву	GREGINAL SIGNED BUT MEANS
	· 		Title	Petroleum Engineer