



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R388.4
Approval expires 12-31-60.

Land Office **Santa Fe**
Lease No. **079177**
Unit **Canyon Largo**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	☒
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 24

1960

Well No. **24** is located **310** ft. from **(N)** line and **1030** ft. from **(E)** line of sec. **24**

N.E. 1/4 Sec. 24

So Blanco Pictured Cliffs

S.W.

S.W.

N.M.P.M.

(Field)

Rio Arriba

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **4900** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud Date **5-18-60**

On **5-19-60**. Total Depth. **110**.

Ran 3 joints, **8 5/8"**, **24 #**, **J-55** casing (**98**) set at **103** with **84** sks. **50-50**

Diamix, **2 # A-6** circulated to surface.

Held **600 #** 30 minutes. **W.O.C.** 12 hrs. Approximate strength after 12 hrs. **-680 #**.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 997**

Farmington, New Mexico

By **ORIGINAL SIGNED B.H. MEANS**

Title **Petroleum Engineer**