Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* Horm approved. Budget Bureau No. 42-R1424. DEPARTMENT OF THE INTERIOR verse side) 5. LEASE DESIGN OF SERIAL NO.

GEOLOGICAL SURVEY				SF 0/9604	12
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this first for the control of th				6. IF IS OF RELIGION	o 1993
1. OIL GAS V				7. ont Acceptathe Sai	COM
WELL WELL X 2. NAME OF OPERATOR	OTHER			S. FARM OR LEASE NAM	
Skelly Oil Compan	y			C. W. Rober	ts
3. ADDRESS OF OPERATOR		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		9. WELL NO.	
1860 Lincoln Stre	et, Denver, Colors	nce with any St	ate requirements.	10. FIELD AND POOL, OF	I WHIDCAT
See also space 17 below.) At surface	•			Oiito_Dakot	a
660' FSL and 660' FWL Section 17, T 25 N, R 3 W				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
Rio Arriba County	, New Mexico			Sec. 17, T	25 N, R 3 W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico	
	7142' GL	715	2' KB	Rio Arriba	New MEXICO
16. C	neck Appropriate Box To	Indicate Na	ture of Notice, Report, or Ot	ther Data	
	OF INTENTION TO:			NT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASIN	;a 🔲	WATER SHUT-OFF	REPAIRING V	VELL
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING C.	<u> </u>
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDON ME:	*T*
REPAIR WELL	CHANGE PLANS		(Other) (Note: Report results of	of multiple completion	on Well
(Other) Te	st Gallup Zone	X	Completion or Recomple details, and give pertinent dates, and measured and true vertical	tion Report and Log to	гш.)
Plans are to test Pull rods and tul Set bridge plug Perforate 5 1/2" 6990'-7000', 6960	ota Field. Product the Gallup Zone oing. at 7400' to cover 17# casing at 7230'-6970'. ,000# sand down 3	tion has bas follows the Dakota	a perforations. 7110'-7120', 7125'-7	eriorations.	
(This space for Federal o	foregoing is true and correct		rea Superintendent	DATE Dec.	. 17, 1973
APPROVED BYCONDITIONS OF APPRO	OVAL, IF ANY:	TITLE		DATE	