



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. 12  
Unit 12/4

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>XXX</b>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 20, 199

**Schultz Hill**  
Well No. 12 is located 1190 ft. from S line and 750 ft. from 12 line of sec. 13  
12/4 Section 13 (1/4 Sec. and Sec. No.) 23-N (Twp.) 3-W (Range) 12 (Meridian)  
So. Blanco P. C. Ext. (Field) Rio Arriba County (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7248 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was found non-productive after drilling to 3020' RKB.  
Benson-Martin-Greer Drilling Corporation personnel talked with Mr. P. T. McGrath and developed the following program for plugging and abandoning:

Set cement plugs - 3760-3830 feet - 40 sacks  
3560-3830 feet - 40 sacks  
10 sacks in top of 8-5/8" casing left in hold  
Erect dry hole marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Frank A. Schultz  
Address Box 720  
Farmington, New Mexico

By [Signature]  
C. Benson Neal, Agent in Farmington  
Title \_\_\_\_\_