



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4.  
Approval expires 12-31-60.

Indian Agency \_\_\_\_\_

**Jicarilla Apache**

Allottee \_\_\_\_\_

Lease No. **Jicarilla Contract 148**  
**Tract 245**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Farmington, New Mexico** **May 29**, 19 **56**

**Jicarilla Contract 148**

Well No. **7** is located **990** ft. from **[S]** line and **990** ft. from **[E]** line of sec. **15**

**SE/4 of Section 15**

**T-25-N**

**R-5-W**

**NMPH**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

**South Blanco-Pictured**  
**Cliffs**

**Rio Arriba**

**New Mexico**

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the ~~surface~~ **ground level** above sea level is **6886** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On March 25, 1956, this well was spudded and on March 27, 1956, 8-5/8" casing was landed at 151 feet and cemented with 100 sacks cement. After waiting on cement for 16 days casing and water shut off were tested with 500 pounds for 30 minutes with no drop in pressure.

On May 8, 1956, 5 1/2" casing was landed at 3160 feet and cemented with 100 sacks cement. After waiting on cement for 24 hours casing and water shut off were tested with 500 pounds for 30 minutes with no drop in pressure. Completion operations were resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **STENOLIND OIL & GAS COMPANY**

Address **P.O. Box 177**  
**Farmington, N.M.**

By **L.D. Spivey**

Title **Field Superintendent**