1 2

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Jicarilla Tribal

Less No. Contract No. 145

UniSE/4 Sec. 12, T-25N,

R-5W N.H.P.M., Rio Arriba

County, New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

	NTENTION TO DRILL	į į	SUBSEQUENT REPOR	T OF WATER SHUT-OF	FF	IX !
	NTENTION TO CHANGE PLANS		1	T OF SHOOTING OR A		1
	NTENTION TO TEST WATER SHUT-			T OF ALTERING CASH		
	NTENTION TO RE-DRILL OR REPAI			T OF RE-DRILLING OF		
	NTENTION TO SHOOT OR ACIDIZE		l)	T OF ABANDONMENT		
	NTENTION TO PULL OR ALTER CA		SUPPLEMENTARY WE			
	NTENTION TO ABANDON WELL				man grant grant grant	ED
 	(INDICATE ABOVE	BY CHECK MARK NAT	URE OF REPORT, NOTIC	CE, OR OTHER DATA)		
				•		
				June 2		, 1958
	K Jicarill cated 79	·	- ,	Ç	line of sec.	12
M/L, S	E/L Section 12 2 c, and Sec. No.)	SN 5W Twp.) (Ran	ge) (Meridian)		
					Leo	
outil E	lanco-Pict. Of.	(County or Sul	odivision)	(State or	r Territory)	
	ion of the derrick floor a	DETAILS	OF~WORK	proposed casings; incoverk)	dicate unuddiad jo	be, colpon
ate names o		DETAILS sands; show sizes, w points, and all other	OF~WORK	proposed casings; inwork)	dicate myddiol Po	on)
ate names o	f and expected depths to objectiv ing	DETAILS sands; show sizes, w points, and all other 6, 1958 8, 32.3#, Ha ed w/125 sac	OF WORK eights, and lengths of important proposed v	asing. Land	led at	JOM J
ate names o	Spudded well May 1 Ran 3 joints 9 5/8	DETAILS sands; show sizes, w points, and all other 6, 1958 8, 32.3#, Hw sci w/125 sac y 16, 1958.	OF WORK eights, and lengths of important proposed v 10 surface c ks regular v	asing. Land	led at chloride.	om)
1- 2-	Spudded well May 1 Ran 3 joints 9 5/8 104 R.K.B. Cement Plug down 10 PM Ma	DETAILS sands; show sizes, w points, and all other 6, 1958 8, 32.3#, Hand w/125 saccy 16, 1958. ested w/800	OF WORK eights, and lengths of important proposed v 10 surface c ks regular v psi pressure	asing. Land /2% calcium on May 17,	led at chloride.	
1- 2- I understan	Spudded well May 1 Ran 3 joints 9 5/8 104 R.K.B. Cement Plug down 10 PM Na Drilled plug and t pressure held.	DETAILS sands; show sizes, w points, and all other 6, 1958 8, 32.3#, Hand w/125 saccy 16, 1958. ested w/800 ceive approval in write	OF WORK eights, and lengths of important proposed v 10 surface c ks regular v psi pressure	asing. Land /2% calcium on May 17,	led at chloride.	
1- 2-	Spudded well May 1 Ran 3 joints 9 5/8 104 R.K.B. Cement Plug down 10 PM Ma Drilled plug and t pressure held.	DETAILS a sands; show sizes, w points, and all other 6, 1958 32.3#, Have a w 60 w 125 sacc w 16, 1958. ested w 800 ceive approval in writh 8 Company	OF WORK eights, and lengths of important proposed v 10 surface c ks regular v psi pressure	asing. Land /2% calcium on May 17, Survey before operati	led at chloride. 1958	
1- 2- I understan	Spudded well May 1 Ran 3 joints 9 5/8 10h; R.K.B. Cement Plug down 10 PM Na Drilled plug and t pressure held. nd that this plan of work must re Southern Union Ga	DETAILS a sands; show sizes, w points, and all other 6, 1958 32.3#, Have a w 60 w 125 sacc w 16, 1958. ested w 800 ceive approval in writh 8 Company	OF WORK eights, and lengths of important proposed v 10 surface c ks regular v psi pressure	asing. Land /2% calcium on May 17,	led at chloride. 1958	