


(SUBMIT IN TRIPPLICATE)

Land Office Santa Fe  
Lease No. 079177  
Unit Canyon Largo UnitUNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SCHULTZ, TURNER, FIELDS-GOVERNMENT #1-9: August 8, 1956Well No. 1-9 is located 919 ft. from N line and 919 ft. from E line of sec. 9S2/4 Section 9  
(1/4 Sec. and Sec. No.)25-N  
(Twp.)1-6N  
(Range)101W  
(Meridian)Wildcat  
(Field)Midland  
(County or Subdivision)New Mexico  
(State or Territory)(Canyon Largo) The elevation of the derrick floor above sea level is 6588 ft. KB (Estimated)

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8-5/8" Casing @ 101' w/70 sax.ID: 2735' Top of Pictured Cliffs: 2639 (13942)

Ran open end drill pipe to 2690 &amp; equalized 40 sax cmt. Pulled DP to 2200' and equalized 60 sax Regular. Placed 15 sax plug in top of 8-5/8" casing. Placed 4-1/2" marker 4' above ground &amp; cleaned up location.

Plugged & Abandoned 8-8-56:

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Superior Oil CompanyAddress Midland, TexasBy W. J. Mothis (W. J. Mothis)Title Petroleum Engineer

113-194

113-194

113-194

113-194

113-194

113-194

113-194

113-194

113-194

