


Form 9-381a
(Feb. 1951)



(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No. 09335-A
Unit Feder 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 10-1-C is located 1700 ft. from [N] line and 1140 ft. from [E] line of sec. 20

37 (1/4 Sec. and Sec. No.) 21 (Twp.) 21 (Range) 10 (Meridian)
Gravelly P. C. Co. (Field) San Antonio (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7435 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On 11-24-59 Top of hole 3723'.
Run 91 joints 5 1/2", J-55, 15.5 lb casing (3712') set at 3722' with 13 sacks
regular cement, 13 sacks diamix, 1/4 cu. ft. Grout-Crete 6"/sk. & 2% Cel,
followed with 50 sacks neat cement.

Held 1000#/30 minutes.

Top of cement by temperature survey at 3720'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997
Farmington, New Mexico

By ORIGINAL SIGNER, GUY MEANS
Title Petroleum Engineer