

(SUBMIT IN TRIPLICATE)

Indian Agency Albuquerque

Contract #122

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 194082

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

~~CHARILLA APACHE TRACT "C"~~

Farmington, New Mexico April 16, 1957

Well No. 1 is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 10
NE 1/4 of NE 1/4 Sect. 10 T-25-N R-24-W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Field Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded at 1:00 A.M., 4/12/57.

4/13/57: Set 23-3/8" casing at 309' w/395 lbs. 3% calcium chloride cement. PCB at 8:55 A.M., 4/14/57. Cement circulated.

4/16/57: Tested casing w/200# for 30 minutes - OK. Drilled plug at 9:00 A.M., 4/15/57.



I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Humble Oil & Refining Company

Box 1245

Address Farmington, New Mexico

By R. M. Lilly
Dist. Supt.

Title _____

AM/

