

Land Office Senta Fe Lease No.

Unit Canyon Jargo Unit

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS	
NOTICE OF INTENTION TO DRILL. NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL.	SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT, 6 MAY 9 1958
(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)
	(Range) (Meridian) (Residential Meridian) (Residential Meridian) (Residential Meridian)
The elevation of the derrick floor above sea lev	rel is <u>PRA</u> ft.
	LS OF WORK
State names of and expected depths to objective sands; show size ing points, and all of	es, weights, and lengths of proposed casings; indicate mudding jobs, cement- ther important proposed work)
4-30-58. Total Depth 2034. Ran 72 joints 5 1/2 19.50%, J-55 oregular cement. To sacks Points, 2% regular cement. Held 1000% for 30 minutes. Top of cement by temperature survey	casing (2923) set as 2933 with 50 sacks Gel, 1/4/ Flocele/St, Followed by 50 sacks at 1718.
I understand that this plan of work must receive approval in a Company El Paso Natural Gao Company Address Eox 997	writing by the Geological Survey before operations may be commenced.
Fermington, New Mexico	By And Sand I st a tell
	Title Pokrokoun Anginosk
	GPO 918507