?orm	9-031
May	1963)

HMITED STATES

SUBMIT			
(Other 1	uctions	οn	re-

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 7. OIL WELL A OTHER NAME OF OPERATOR El Paso Natural Gas Company Address of Operator PO Box 990, Farmington, NM 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	SF 078884 IF INDIAN, ALLOTTEE OR TRIBE NAME UNIT AUREEMENT NAME Canyon Largo Unit FARM OR LEASE NAME Canyon Largo Unit WELL NO.	
OIL GAS WELL A OTHER NAME OF OPERATOR El Paso Natural Gas Company ADDRESS OF OPERATOR PO Box 990, Farmington, NM 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	Canyon Largo Unit Canyon Largo Unit WELL NO.	
WELL WELL OTHER NAME OF OPERATOR El Paso Natural Gas Company ADDRESS OF OPERATOR PO Box 990, Farmington, NM 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	Canyon Largo Unit	
El Paso Natural Gas Company Address of Operator PO Box 990, Farmington, NM 87401 Location of Well (Report location clearly and in accordance with any State requirements.*	Canyon Largo Unit	
PO Box 990, Farmington, NM 87401 Location of Well (Report location clearly and in accordance with any State requirements.*	WELL NO.	
PO Box 990, Farmington, NM 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*		
. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10	21	
	34	
See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT	
At surface 990'N, 990'W	So. Blanco Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND	
	SURVEY OR AREA	
	Sec. 12, T-25-N, R-6-W NMPM	
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12	2. COUNTY OR PARISH 13. STATE	
6792'DF	Rio Arriba New Mexico	
6. Check Appropriate Box To Indicate Nature of Notice, Report, or Othe	er Data	
NOTICE OF INTENTION TO SUBSEQUENT	ENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING	
SHOOT OF ACIDIZE ABANDON' SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL CHANGE PLANS (Other) Tubing repla	cementx	
(Other) (NOTE: Report results of a Completion or Recompletion	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, incl proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical de nent to this work.)* 	luding estimated date of starting any epths for all markers and zones perti-	

Pulled 98 joints 2 7/8" tubing. Ran 90 joints 1 1/4" tubing, 2.4#, 10rd 1-25-73 NU IJ J-55 tubing, 2872.66' landed at 2882.66' with pin collar on bottom and bottom 10' perf'd with 2 holes per foot.



18. I hereby certify that the foregoing is true and correct		
signed af Jalent	TITLE Production Engineer	DATE July 27, 1973
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE ↑ 10 73