

(SUEMIT IN TRIPLICATE)

Indian Agency

Jicarilla

UNITED STATES

Contract No. 147

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Co. Lease No. 196183

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|---|-------------------------------------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | Subsequent report of perforating and aqua-froes | <input checked="" type="checkbox"/> |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JICARILLA APACHE TRIBE
OF INDIANS "J"

Farmington, New Mexico May 4, 1956

Well No. 5 is located 990 ft. from N line and 880 ft. from W line of sec. 7
NE 1/4 of NW 1/4 of Sec. 7 25-N 5-W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Blanco Pictured Mts Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6729 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4/1/56: Set 2931', 92 Jm., 5-1/2" casing at 2940' w/175 sacks 10% gel and 100 sacks neat cement. POB at 3:40 P.M., 5/1/56. Rotated while cementing. Cement did not circulate.

4/2/56: Tested casing w/1000# for 30 min. - O.K. Perforated 5-1/2" casing 2842'-2875' w/6 McGullough bullets per ft. Aqua fraced by Dowell w/total of 32,760 gals. water mixed 1 1/2" sand per gal. Flush & overflush 6930 gals. w/1400#. Breakdown pr. 1000#. Treating pr. 1400#. Injection rate 48 bbls./min.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company
Box 1268
Address Farmington, New Mexico

By Russell M. Lilly
Dist. Supt.
Title _____



100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

