


Form 9-831a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 04076
Unit Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 11, 1956

Well No. 3-D is located 60 ft. from S line and 35 ft. from E line of sec. 3

SE Sec. 3 (1/4 Sec. and Sec. No.) 25N (Twp.) 2W (Range) N.M.P.M. (Meridian)

Cavalin (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7434 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-21-58 This well was plugged and abandoned in the following manner:

1. Set cast iron cementing retainer at 3391'.
2. Squashed Pictured Cliffs perforations 3500-30 w/45 sacks cement.
3. Set plug on top of retainer with 5 sacks cement.
4. Set plug at surface with 40 sacks cement.
5. Erected 4" pipe 4' high at surface as permanent marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan Gas CorporationAddress Box 997Farmington, New MexicoAttn: E. S. OberlyBy ORIGINAL SIGNED E. S. OBERLYTitle Agent